


ABN: 32 059 519 541

17/11-21 Underwood Rd

Homebush, NSW 2140


02-9746 7133

BEAMISH ST CAMPSIE









Scope of works:

- Identify water leak
- Conduct water test.
- Develop repair methodology
- Introduce external membrane and drain at base of walls as residence floor below external level
- Negative membrane internal base of wall.
- Installation of parapet flashing
- Repair corroded lintel
- Waterproof external wall