



**CONRINA
REMEDIAL
BUILDING
SOLUTIONS**

ABN: 32 059 519 541

17/11-21 Underwood Rd

Homebush, NSW 2140

02-9746 7133

REVESBY RESIDENTIAL



Scope of works:

- Identify water leak to upstairs bedrooms
- Conduct water leak test
- Methodology for repairs.
- Careful removal of bricks and install new tray flashing.
- Reinstate brickwork.
- Render works ready for painting.